

# TECHNICAL SERVICE BULLETIN

## **GM Full Sized Truck & SUV Overhead Console:**

2001-04 Chevrolet Silverado extended + crew cab

2001-04 GMC Sierra extended + crew cab

2000-04 Chevrolet Tahoe / Suburban

2000-04 GMC Yukon / Yukon XL

2003-04 Chevrolet Avalanche

2002-2004 Cadillac Escalade/EXT

*No console modification required* - relocate (move) the console forward against the windshield to make room for the sunroof. Recover the headliner. Spoiler sunroofs require locating the motor above the console (No QF). Most full size sunroofs fit the flat spot, some just barely ride up on the front edge of the ribs in the roofskin.

This application is NOT suitable for Quick-Fit (exposed trim ring/bezel) sunroof installations. There is insufficient clearance between the B-bow and console. Also, the console will not lay flat over top of a trim bezel. Headliner recover is required.



**DONMAR<sup>®</sup>**  
**SUNROOFS & ACCESSORIES**

1-800-SUNROOF

904/731-3393 · fax 904/731-0004